2024.5.22

# [RECOMMENDATION] Evacuation from Ise Bay and Mikawa Bay

When 4<sup>th</sup> Coast Guard regional Headquarters Commander issues a [RECOMMENDATION] or [NOTICE] for evacuation because of typhoon, Designated vessels should evacuate from Ise Bay and Mikawa Bay to a safe area (outside) with little influence from the typhoon.

When recommendation and notice are issued, we will notify you by Maritime Information and Communication System.

#### 1. Designated Area

Ise Bay (applied Act on Maritime Traffic Safety) and Mikawa Bay (incl. Chita Bay)

2. Designated Vessels

Maritime Information and

Communication System

PA 160m <u>≤</u>	
9A 160m <u>≤</u>	
A 160m <u>&lt;</u>	
LOA 200m ≤	
,000 GT <u>&lt;</u>	

[NOT APPLICABLE]

- ① Domestic liner vessel
- 2 Vessel whose navigation area is [smooth water], [coasting area] or [limited grater coasting area]

## 3. Ise Bay (RECOMMENDATION)

Туре	Detail
Evacuation from Ise Bay to outside	Designated vessels in Ise Bay should evacuate from Ise Bay to a safe area (outside) with little influence of the typhoon in the early stage. However, vessels that are able to stay safely in the area with little influence of the typhoon in Ise Bay are excluded.
Refrain from entering to Ise Bay	Designated vessels that are going to enter lse Bay should refrain from entering lse Bay. However, vessels that are able to stay safely in the area with little influence of the typhoon in lse Bay, or vessels that can evacuate to outside of lse Bay in the early stage are excluded.

Council for typhoon in Ise Bay & Mikawa Bay (4th Regional Coast Guard Headquarters)

### 4. Mikawa Bay (NOTICE)

Туре	Detail		
Evacuation	Designated vessels in Mikawa Bay (incl. Chita Bay) should evacuate from		
from Mikawa	Mikawa Bay to a safe area (outside) with little influence of the typhoon in the		
Bay to	early stage. However, vessels that are able to stay safely in the area with		
outside	little influence of the typhoon in Mikawa Bay are excluded.		
Refrain from entering to Mikawa Bay	Designated vessels that are going to enter Mikawa Bay should refrain from		
	entering Mikawa Bay. However, vessels that are able to stay safely in the		
	area with little influence of the typhoon in Mikawa Bay, or vessels that can		
	evacuate to outside of Mikawa Bay in the early stage are excluded.		

#### 5. No anchoring

During NOTICE is issued in Mikawa Bay,

a : 34-37-43 N	136-58-39 E
b : 34-40-47 E	137-03-47 E
c : 34-43-31 E	137-12-21 E
d : 34-43-12 E	137-12-38 E
e : 34-40-25 E	137-03-55 E
f : 34-37-25 E	136-58-55 E

